

HAB  
OHIO  
9-BEL  
6-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Willis Kelly House  
4735 Guernsey Street  
Bellaire  
Belmont County  
Ohio

HABS No. OH-2322

Photographer: Ben Schneider

June 23, 1988

- OH-2322-1      GENERAL VIEW LOOKING NORTH-WEST GUERNSEY STREET,  
                 BELLAIRE, OHIO.
- OH-2322-2      FRONT, EAST SIDE.
- OH-2322-3      NORTH SIDE.
- OH-2322-4      BACK, WEST SIDE.
- OH-2322-5      SOUTH SIDE.
- OH-2322-6      ROOF DETAIL, LOOKING NORTH-EAST.
- OH-2322-7      FRONT DETAIL, LOOKING WEST.
- OH-2322-8      FRONT DETAIL, LOOKING NORTH-WEST.
- OH-2322-9      FRONT DETAIL, LOOKING WEST.
- OH-2322-10     INSIDE FRONT DOORWAY.
- OH-2322-11     INSIDE DETAIL.    FIRST FLOOR, SOUTH-EAST ROOM.
- OH-2322-12     INSIDE DETAIL.    ARCHED DOORWAY. SOUTH MIDDLE ROOM.
- OH-2322-13     INSIDE DETAIL.    FRONT STAIRWAY AND HALLWAY.  
                 LOOKING TOWARD FRONT DOOR.
- OH-2322-14     INSIDE DETAIL.    FRONT-MIDDLE WINDOWS AND LOCKERS.  
                 UPSTAIRS-FRONT HALLWAY.
- OH-2322-15     INSIDE DETAIL.    LOOKING EAST DOWN FRONT STAIRWAY.
- OH-2322-16     INSIDE DETAIL.    LOOKING WEST DOWN BACK STAIRWAY.
- OH-2322-17     SERVANTS QUARTERS, GARAGE, LOOKING NORTH-WEST.